PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.	Dated: 18125
It is certified that an inspection team headed	by Loub leading Mr. Ratash.
	PHC Coolihalli. (Lab feelviran).
(Name of Department/ Office) inspected the	DMO office. Ramunaquera,
(Name & Address of the school) on29	10+125 mate of Merocian) and found that the
DKS Hill View Public School	O.L(Name of school) has safe drinking water
facilities for the students and members of st	aff of the institution and is maintaining the hygienic
sanitation condition in the school building & t	he campus as per norms prescribed by the Central/
State/ U.T. Govt.	

The above is valid for a period of ... 3 Worths,

Signature with Seal:

W. Wanix she happing To:

Name

Designation

Name & Address of the Office / Department :

To

DKS Hill View Public School Rampuradodd: [v] kod: halli [v] Kanakapura - 562119

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

> DKS Hillview Public School Affiliated to CBSE-831291 Rampuradoddi, Kodihalli (H) Kanakapura: Ramanagara

en Romanad